BEECH 90

Accessories Required For Smokejumping:

Primary Floor Anchor: MEDC-617- Anchor cable for Beech 90, 99, 100,

& 200 & Nomad N24A Series Aircraft

STC Strength: 2,000 pounds

STC #: SA566NW

Other Accessories: MEDC-643- Handrail & Wind Deflector for Beech

90, 99, 100, & 200 Series Aircraft

MEDC-644 Floor Panels for Beechcraft 90, 99,

100 & 200 Series Aircraft

Jump Step & Attachment:

Jump step not used on Beech 90

Note: There is no secondary anchor design for the Beech 90.

BEECH 99A

Accessories Required For Smokejumping:

Primary Floor Anchor:

MEDC-617- Anchor cable for Beech 90, 99, 100,

& 200 & Nomad N24A Series Aircraft

STC Strength: 2,000 pounds

STC #: SA566NW

Secondary Anchor:

MTDC-809- Horizontal Anchor Track for Beech

99A

STC Strength: 750 pounds

STC #: SA4047NM

Other Accessories:

MEDC-643- Handrail & Wind Deflector for Beech

90, 99, 100, & 200 Series Aircraft

MEDC-644 Floor Panels for Beechcraft 90, 99,

100 & 200 Series Aircraft

Jump Step & Attachment:

MEDC-759- Stepbasket (universal), Smokejumper

Aircraft

MEDC-794- Universal Step Strut

MEDC-785 Jump Step Attachment Points, Beech

99

Note: The Beech 99 requires a door brace between the aft air stair door and the forward jump door. Contact MTDC for information about this accessory.

KING AIR 200

Accessories Required For Smokejumping:

Primary Floor Anchor:

MEDC-617- Anchor cable for Beech 90, 99, 100,

& 200 & Nomad N24A Series Aircraft

STC Strength: 2,000 pounds

STC #: SA566NW

Secondary Anchor:

Pending

Other Accessories:

MEDC-643- Handrail & Wind Deflector for Beech

90, 99, 100, & 200 Series Aircraft

MEDC-644 Floor Panels for Beechcraft 90, 99,

100 & 200 Series Aircraft

Jump Step & Attachment:

MEDC-759- Stepbasket (universal), Smokejumper

Aircraft

MEDC-794- Universal Step Strut

Note: Contact MTDC for information about step attachment configuration for the King

Air 200.

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA566NW

This certificate, issued to U. S. Forest Service

cortifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the niver thiness requirements of Part

Regulations.

*See attached Master Eligibility List (MEL) Priginal Hadact - Type Cartificate Jumber: No. SA566NW for list of approved aircraft Muke: models and applicable airworthiness regulations.

Malet:

Description of Type Design Change Installation of a Parachute Deployment Static Line Attachment System in accordance with U.S. Forest Service Specification and Installation Instructions; and Drawing MEDC-617, Sheets 1 and 2.

The static line and anchors are attached to the Beech (Aeroquip) R.H. Seat track.

Limitations and Conditions: The approval of this change in type design applies basically to the above model aircraft only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate, Addendum No. SA566NW, and MEL No. SA566NW shall be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until sur-

rendered suspended revoked, or a termination date is atherwise established by the Eldministrator of the

Federal Aviation Administration.

Sale of application: January 25, 1978

Sale ressued:

Late of issuance: March 27, 1978

Tate amended: July 14, 1982

By difection of the Administrator

Mark E. Baldwin, (Signature) Chief,

Denver-Aircraft Certification Field Office Northwest Mountain Region, Aurora, Colorado

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.



DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION NORTHWEST MOUNTAIN REGION ver Aircraft Certification Field Office

Denver Aircraft Certification Field Office 10455 East 25th Avenue - Suite 307 Aurora, Colorado 80010 (303) 340-5302 or 5569

July 14, 1982

USDA Forest Service Equipment Development Center Building 1, Fort Missoula Missoula, Montana 59801

Gentlemen:

Project No. A687RM-S

We have satisfactorily completed our evaluation of the amendment to Supplemental Type Certificate (STC) SA566NW. The STC has been amended to increase the maximum allowable load on the static line anchor cable to 2420 pounds. Also, Item II on the Master Eligibility Listing (MEL) was amended to include the Beech Model Series 100 aircraft. The specification and installation instructions have also been amended to increase the load to 2420 pounds and include a statement concerning the slack in the cable assembly.

A copy of the amended certificate, MEL, and installation instructions are enclosed. Please return your previously issued STC to this office for cancellation.

As recipient of this approval, except as provided in Federal Aviation Regulations (FAR) Part 21.3(d), you are required to report any failure, malfunction, or defect in any product or part manufactured by you that you have determined has resulted or could result in any of the occurrences listed in FAR Part 21.3(c). The report should be communicated initially by telephone and subsequently in writing to the Chief, Denver Aircraft Certification Field Office, ANM-170D, at the telephone number and address indicated above. This first contact shall take place within 24 hours after it has been determined that the failure required to be reported has occurred. Federal Aviation Administration Form 8330-2 (Malfunction or Defect Report) or any other appropriate format is acceptable in transmitting the required details.

If you plan to manufacture or sell parts for installation on type certificated aircraft, please review FAR Part 21.303 which is applicable to replacement and modification parts. Applications for Parts Manufacturer Approval

may be made in letter form, listing the following information: (1) part name, (2) part number, (3) STC number, (4) model or type certificated product on which the part will be installed, and (5) a statement certifying that a fabrication inspection system has been established in accordance with FAR Part 21.303(h). This application should be mailed to the address indicated above.

Sincerely,

Mark E. Baldwin

Chief, Denver Aircraft

Certification Field Office

3 Enclosures

United States of America

Department of Transportation—federal Abiation Administration

Supplemental Type Certificate

(Continuation Sheet) July 14, 1982

Number SA566NW

SUPPLEMENTAL TYPE CERTIFICATE ADDENDUM NO. SA566NW

The conditions and limitation of Type Certificate Data Sheet Nos 3A2O, A14CE and A24CE apply except where superseded by the following:

This Supplemental Type Certificate Data Sheet, which is part of STC SA566NW, prescribes the conditions and limitations under which the product for which the STC was issued meets the airworthiness requirements of the Federal Aviation Regulations:

SUPPLEMENTAL TYPE CERTIFICATE HOLDER: United States Forest Service

I. BEECH MODEL SERIES 90, 99,100 AND 200 AS MODIFIED BY STC SA566NW

Airframe: No change

Engines: No change

Performance: No change

Limitations: No change

Placards: The following PLACARDS must be located near the Cargo Door that reads:

- (1) THE MAXIMUM ALLOWABLE LOAD ON THE STATIC LINE ATTACH CABLE IS 2420 POUNDS IN A TYPICAL PARACHUTE DEPLOYMENT CONFIGURATION
- (2) THE CABLE STOP MUST BE ADJUSTED ALONG THE LENGTH OF THE CABLE SO THAT THE PARACHUTE DEPLOYMENT BAG CANNOT TRAIL AFT OF THE HORIZONTAL STABILIZER

NOTE: A determination was made that Supplemental Type Certificate SA566NW does not effect aircraft performance; therefore, no Airplane Flight Manual Supplement change was deemed necessary.

-END-

SPECIFICATION AND INSTALLATION INSTRUCTION FOR SMOKEJUMPER STATIC LINE ANCHOR CABLE FOR BEECHCRAFT MODELS 90, 99, 100, AND 200 SERIES AIRCRAFT

Part

Load

Static Line Anchor Cable

2420# 1/

1/ Load applied in a typical parachute deployment configuration with static line routed through the carabiner on the rear anchor.

Parts are fabricated as illustrated in drawing MEDC-617 sheets 1 and 2. All welding is by the arc process. Assembled anchor units are installed in the aircraft right hand seat track with the one using Part 24, side brace, placed opposite the door used for jumper deployment. Cable length between anchors shall be of adequate length to allow all jumpers to attach their deployment static line without having to move aft in the cabin. This will facilitate emergency evacuation. The cable assembly shall be installed with 4 inches of slack measured in extreme spread. Part #18 the cable stop must be adjusted along the length of the cable so the parachute deployment bag cannot trail aft of the horizontal stabilizer.

All assemblies fabricated from steel are to be painted with zinc chromate P-27 or equivalent corrosion protecting prior to intallation in the aircraft.

Amended July 14, 1982

FA PPROVED

MASTER ELIGIBILITY LISTING NUMBER SA566NW FOR

PARACHUTE DEPLOYMENT STATIC LINE ATTACHMENT SYSTEM

U.S. FOREST SERVICE

DATE: March 27, 1978

`EM	AIRCRAFT MAKE	AIRCRAFT MODEL	ORIGINAL TYPE CERTIFICATE NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA SEALED DRAWING/ DRAWING LIST NUMBER REV.	AFM SUPPLEMENT NUMBER/ DATE	MEL AMENDMENT DATE
	Beech	65-90, 65-A90, 65-A90-1 65-A90-2 65-A90-3 65-A90-4 B90, C90, E90	3A20 (Rev.32)	CAR 3 eff. May 15, 1956 w/Amendments (See T.C. 3A20 page 24 for details)	U.S. Forest Service Dwg. No. MEDC-617 (Sheets 1 & 2)		
I	Beech	99, 99A, A99 A99A, B99, 100 A100, A100A, A100C, B100	A14CE	Part 23, dated 2/11/65 w/Amendments (See T.C. A14CE, page 15 for details)			July 14, 1982
II .	Beech	200, A200, 200T	A24CE	Part 23, dated 2/1/65 w/Amendments (See T.C. A24CE, Page 6 for details)		e e e e e e e e e e e e e e e e e e e	
· V	Beech	H18, E18S, C-45G, C-45H	A-765	CAR 03, 11-13-45 CAR 3, 11-1-49 as amended by 3-14	U.S. Forest Service Dwg. No. MEDC-617, Sheets 1 and 2	,	April 12, 1979
				·			



DEPARTMENT OF TRANSPORTATION

FEDERAL AVIATION ADMINISTRATION NORTHWEST MOUNTAIN REGION Denver Aircraft Certification Field Office 10455 East 25th Avenue - Suite 307 Aurora, Colorado 80010 (303) 340-5302 or 5569

July 29, 1982

USDA Forest Service Equipment Development Center Building 1, Fort Missoula Missoula, Montana 59801

Gentlemen:

Project No. A687RM-S

We have satisfactorily completed our review of your drawing, MEDC-617, revision D, sheets 1 and 2.

Sheet 1 has been revised since the issuance of the amendment to Supplemental Type Certificate (STC) SA566NW, dated July 14. This revision added the length of the anchor cable and changed Note 3 to increase the cable assembly slack from 4 to 6 inches. This change on the drawing necessitates an amendment to the Specification and Installation Instruction.

Enclosed is a Federal Aviation Administration approved copy of the Specification and Installation Instruction, dated July 29, 1982, and drawing MEDC-617. Please return your previously issued STC to this office for cancellation.

Sincerely,

F. S. AUG 2 1982

MEDC

Woodford R. Boyce

Acting Manager, Denver Aircraft

Certification Field Office

2 Enclosures

SPECIFICATION AND INSTALLATION INSTRUCTION FOR SMOKEJUMPER STATIC LINE ANCHOR CABLE FOR BEECHCRAFT MODELS 90, 99, 100 AND 200 SERIES AIRCRAFT

Part

Load

Static Line Anchor Cable

2420# 1/


1/ Load applied in a typical parachute deployment configuration with static line routed through the carabiner on the rear anchor.


Parts are fabricated as illustrated in drawing MEDC-617 sheets 1 and 2. All welding is by the arc process. Assembled anchor units are installed in the aircraft right hand seat track with the one using Part 24, side brace, placed opposite the door used for jumper deployment. Cable length between anchors shall be 76 1/2 inches. The cable assembly shall be installed with 6 inches of slack measured in extreme spread. Part #18, the cable stop, must be adjusted along the length of the cable so the parachute deployment bag cannot trail aft of the horizontal stabilizer.


All assemblies fabricated from steel are to be painted with zinc choromate P-27 or equivalent corrosion protection prior to installation in the aircraft.

Amended July 14, 1982

Amended July 29, 1982







• TOP BRACE **(** 3 LOCATE AND WELD AT ASSY 132R SIDE BRACE © 7 TWO SCREWS USED IT COUT AND FORM WIND DEFLECTOR TO OUTSIDE OF AIRCRAPT FROM RAIN GUTTER TO BELOW DOOR THRESHOLD AND APPROX. 3-INCHES FOREWARD OF OPENING. DRILL AND RIVET AS REGISTED. WIND DEFLECTOR INCO I PARTY 2-8

I PARTY 2-8 U.S. DEPT. OF AGRICULTURE FOREST SERVICE EQUIPMENT DEVELOPMENT CENTER HANDRAIL & WIND DEFLECTOR FOR BEECHCRAFT 90,99,100, \$200
SERIES AIRCRAFT SHEET L OF L MEDC-643 ħ.

0

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

Number SA4047NM

This certificate, issued to USDA Forest Service
Missoula Technology and Development Center

cortifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation

Regulations.

Criginal Breduct - Type Certificate Number: A14CE
Make: Beech
Medel: 99A

Description of Type Design Change: Installation of horizontal anchor track and tether system for cargo spotter.

Limitations and Conditions:

1. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any other previously approved modification will introduce no adverse effect upon the airworthiness of the aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Tederal Sviation Administration.

Gale of application: October 31, 1988

Dute reissued :

Dute of issuance: April 25, 1989

Date amended :

TRAI AVIATION Z

Brydirection of the Administrator

MICHAEL H. BORFITZ, (Signature) Supervisor Denver Aircraft Certification Field Office Northwest Mountain Region, Aurora, Colorado

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.



NORTHWEST MOUNTAIN REGION
Denver Aircraft Certification Field Office
10455 East 25th Avenue, Suite 307
Aurora, Colorado 80010
(303)370-5575

April 25, 1989

USDA Forest Service Missoula Technology and Development Center Building No. 1, Ft. Missoula Missoula, Montana 59801

Project No. ANM-100D-0188

Gentlemen:

We have completed our evaluation of your Supplemental Type Certificate (STC) project and find that you have satisfactorily demonstrated compliance with the applicable certification regulations. Accordingly, we have enclosed STC No. SA4047NM dated April 25, 1989, for the installation of a horizontal anchor track and tether system for cargo spotter in a Beech Model 99A.

This STC is official FAA approval of your installation and may be used to authorize identical installations on other aircraft of the same model, subject to the limitations noted on the certificate. It may be transferred or otherwise made available to another party by means of a licensee arrangement in accordance with Federal Aviation Regulations (FAR) 21.47. You are requested to advise your local office within 30 days after the transfer when you transfer or grant licensee rights to the STC in order that we may take the necessary recording or reissuance action.

As recipient of this approval, except as provided by FAR 21.3(d), you are required to report any failure, malfunction, or defect in any product or part manufactured by you that you have determined has resulted or could result in any of the occurrences listed in FAR 21.3(c). The report should be communicated initially by telephone to the Supervisor, Denver Aircraft Certification Field Office, telephone number (303) 340-5575, within 24 hours after it has been determined that the failure has occurred. In addition, written notification to the Supervisor at the above address is required. FAA Form 8010-4, Malfunction or Defect Report, or any other appropriate format is acceptable in transmitting the required details.

If you plan to manufacture replacement or modification parts for sale in conformance with approved data listed on the Certificate, you are required to comply with FAR Part 21.303. A Parts Manufacturer Approval (PMA) may be issued under the provisions of FAR 21.303(d) when you submit a statement certifying that you have established a fabrication inspection system as required by FAR 21.303(h). The identification requirements for parts produced under a PMA are in FAR 45.15. Your statement may be in letter form, with a reference to the STC number, and should be mailed to the address indicated above.


Sincerely,

Michael H. Borfitz

Supervisor, Denver Aircraft Certification

Field Office

Enclosure



٥ LOONTE TRACK ALONG INSIDE EDGE OF STARBOARD CEILING PANEL MALE STATE OF THE (1) BRACKET- ASIDE (V)(3)(3) ξĺΘ (j) STA. 176. 25 NO BRICKET (2) BRACKET-ACUTOUT (S) -1%→ \$\ \ \ 16 RADIUS ωķν (4) BRACKET-B CUTOUT 244 57A-207/25 ()(3)(3) asin STA 226,875 3) BRACKET-BSIDE () () () +32+ (S) (5) & ANGLE BRACKET-ASIDE (2) (±) **STA. 271. 50 NO BRACKET**(a)
(a) * (X) REF See see **Q** 244 ()3/3) STA 325.00 . (24)25 AEF 1° AUGLE BREAK #21 DRILL (6) 4" ANGLE BRACKET-BSIDE U.S. DEPT. OF AGRICULTURE
FOREST SERVICE
TECHNOLOGY & DEVELOPMENT CENTER
MISSOULA, MONTANA HORIZONTAL ANCHOR TRACK SHEET 2 of 4 → 9/8 9/8 5/8 000 BEECHCRAFT 99A TRACK BREAK DETAIL 5000 AGDRILL BANKETS AT STATION
#265,75 AND USE THREE ANG 4A
BRITS WITH LOCK NUT AC366-1032.
REDRILL WITH 732 DRILL BIT. MTDC-809 3/2 1 3 3 В D

١,

 $\overline{()}$

