

Suppression Repair

Windy Rock
MT-SWS-256444
09/28/2025 Day
 6166 acres as of 09/26/2025 1100 MDT
 Map Created: 9/27/2025 20:50

- Other Property
- Division Break
- Safety Zone
- Hazard
- Hellspot

- Lookout
- Medical Drop Point
- Closure
- Staging Area
- Dip Site
- Draft Site

- Mobile Weather Unit
- Repeater
- Value at Risk
- Other
- Landmark
- Gate


- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck
- Slash Pile
- Fence - Cut/Damaged
- Dozer Push

- Culvert
- Clean Up Area
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Plow Line

- Completed Road as Line
- Access Route
- Other
- Repair Line
- Road Repair
- Wildfire Perimeter
- In Use - Fire Management

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- In Use - Fire Management
- Needs Assessment


- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments



0 0.25 0.5 Miles
 1:14,824 | CAT
 IR and Mixed Methods
 NAD 1983 2011 Datum, Lat/Long Grid



Suppression Repair



Suppression Repair

Windy Rock
MT-SWS-256444
09/28/2025 Day
 6166 acres as of 09/26/2025 1100 MDT
 Map Created: 9/27/2025 20:52

- Other Property
- Water Tank
- Division Break
- Safety Zone
- Hazard

- Mobile Weather Unit
- Internet Access
- Repeater
- Value at Risk
- Other
- Landmark
- Gate


- Bridge
- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck
- Slash Pile
- Fence - Cut/Damaged
- Dozer Push

- Culvert
- Clean Up Area
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Plow Line
- Completed Road as Line

- Access Route
- Other
- Repair Line
- Road Repair
- Wildfire Perimeter
- In Use - Fire Management
- Needs Assessment
- Repair Needed

- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments
- In Use - Fire Management
- Needs Assessment
- Repair Needed


- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments



0 0.25 0.5 Miles
 1:16,529 | CAT
 IR and Mixed Methods
 NAD 1983 2011 Datum, Lat,Long Grid



Suppression Repair



Suppression Repair

Windy Rock
 MT-SWS-256444
 09/28/2025 Day
 6166 acres as of 09/26/2025 1100 MDT
 Map Created: 9/27/2025 20:54

- Other Property
- Water Tank
- Division Break
- Safety Zone
- Hazard

- Helispot
- Unimproved Landing Area
- Lookout
- Medical
- Drop Point
- Dip Site
- Draft Site

- Mobile Weather Unit
- Internet Access
- Repeater
- Value at Risk
- Drop Point
- Landmark
- Gate


- Bridge
- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck
- Slash Pile
- Fence - Cut/Damaged
- Dozer Push

- Culvert
- Clean Up Area
- Completed Fuel Line
- Completed Dozer Line
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Plov Line
- Completed Road as Line

- Access Route
- Other
- Repair Line
- Road Repair
- Wildfire Perimeter
- In Use - Fire Management
- Needs Assessment
- Repair Needed

- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments
- In Use - Fire Management
- Needs Assessment
- Repair Needed


- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments



0 0.25 0.5 Miles
 1:17,257 | CAT
 IR and Mixed Methods
 NAD 1983 2011 Datum, Lat/Long Grid



Suppression Repair



Suppression Repair

Windy Rock
 MT-SWS-256444
 09/28/2025 Day
 6166 acres as of 09/26/2025 1100 MDT
 Map Created: 9/27/2025 20:56

- Other Property
- Division Break
- Safety Zone
- HeliSpot
- Medical

- Drop Point
- Staging Area
- Draft Site
- Mobile Weather Unit
- Repeater
- Value at Risk

- Other
- Landmark
- Gate
- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck

- Slash Pile
- Fence - Cut/Damaged
- Dozer Push
- Clean Up Area
- In Progress
- Completed Fuel Break
- Completed Hand Line

- Completed Mixed Construction Line
- Completed Plow Line
- Completed Road as Line
- Access Route
- Other
- Repair Line
- Road Repair

- Wildfire Perimeter
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments

1:11,118 | CAT
 IR and Mixed Methods
 NAD 1983 2011 Datum, Lat/Long Grid

0 0.25 0.5 Miles

Suppression Repair